



### Air Monitor 5

Southwest of Containment Area, Upwind of Site Activities




# Air Monitor 1

Southeast of Containment Area, Downwind of Material Placement



# Air Monitor 6

East of Low Haz Pile, Downwind of Mine Fissure Road Cut



# Air Monitor 7

South of Support Zone, Downwind of Installation of Construction Entrance at Woodlawn St. Gate

