



Air Monitor 1

East of CA, Downwind of CA Material Placement




Air Monitor 2

South of CA, Sulphur Creek Monitoring



Air Monitor 3

South of SWNW, Downwind of Area D/E Excavation



The Action Level for this area is 0.094 mg/m³

All results are below the Action Level

Air Monitor 4

Southwest of CA, Upwind of Site Activities

