


Air Monitor 1

East of CA, Downwind of CA Material




The Action Level for this area is 0.094 mg/m³

All results are below the Action Level


Air Monitor 2

South of CA, Sulphur Creek Monitoring



Air Monitor 3

East of Delaware St., Downwind of Delaware St. Excavation



Air Monitor 4

Southwest of CA, Upwind of Site Activities

