



# Air Monitor 3 Test 1

East of Containment Area, Downwind of Material Placement




# Air Monitor 3 Test 2

East of Containment Area, Downwind of Material Placement



# Air Monitor 5

Southwest of Proposed Sediment Basin, Upwind of Site Activities



22 Fri Aug 2008

Date & Time

# Air Monitor 6

East of High Haz Pile, Downwind of High Haz Pile Excavation

