



Air Monitor 2

East of Pennsylvania Department of Environmental Protection Trailer within Support Zone, Upwind of Site Activities




Air Monitor 4

West of Containment Area, Downwind of Area G Material Placement



Air Monitor 6

North of Containment Area, Downwind of Area G Excavation



The Action Level for this area is 0.028 mg/m³

All results are below the Action Level