

Co-Located Lead Sample Result for Working Hours

Week of June 15, 2009

On October 15, 2008, the United States Environmental Protection Agency (USEPA) lowered the National Ambient Air Quality Lead Standard from a quarterly average of 1.5 µg/m³ to a rolling three-month average of 0.15 µg/m³, effective October 2009. The method of collecting the samples did not change. The current standard for the Site is 1.5 ug/m³.

Date	Sample ID	Sample Location	Result ug/m ³	Co-located with
6/15/09	061509-WH-AM3	Downwind of Areas H excavation.	0.099	Air Monitor #3
6/15/09	061509-WH-PDS	Eastern corner of Delaware Street perimeter fence line.	<0.040	Not co-located with a dust monitor.
6/16/09	061609-WH-AM2	South of the Containment Area, Sulphur Creek Monitoring.	<0.093	Air Monitor #2
6/17/09	061709-WH-PGS1	On Grove Street near corner of Delaware Street perimeter fence line.	<0.057	Not co-located with a dust monitor.
6/17/09	061709-WH-PGS2	On Grove Street perimeter fence line; approximately 190 feet down from the corner of Grove and Delaware Streets; down wind of the Containment Area.	<0.077	Not co-located with a dust monitor.
6/17/09	061709-WH-AM3	Downwind of Delaware Street excavation.	<0.073	Air Monitor #3
6/17/09	061709-WH-PDS1	On the southern side of Delaware Street on the wooden sign.	<0.056	Not co-located with a dust monitor.
6/17/09	061709-WH-PDS2	Delaware Street perimeter fence line.	<0.101	Not co-located with a dust monitor.
6/17/09	061709-WH-AM2	South of the Containment Area, Sulphur Creek Monitoring.	<0.050	Air Monitor #2
6/18/09	061809-WH-PGS1	On Grove Street near corner of Delaware Street perimeter fence line.	<0.142	Not co-located with a dust monitor.
6/18/09	061809-WH-PGS2	On Grove Street perimeter fence line; approximately 190 feet down from the corner of Grove and Delaware Streets; down wind of the Containment Area.	<0.060	Not co-located with a dust monitor.
6/18/09	061809-WH-AM3	Downwind of Grove Street excavation.	<0.094	Air Monitor #3

6/18/09	061809-WH-PDS1	On the southern side of Delaware Street on the wooden sign.	<0.071	Not co-located with a dust monitor.
6/18/09	061809-WH-PDS2	Delaware Street perimeter fence line.	<0.071	Not co-located with a dust monitor.
6/18/09	061809-WH-AM2	South of the Containment Area, Sulphur Creek Monitoring.	<0.065	Air Monitor #2
6/19/09	061909-WH-PGS1	On Grove Street near corner of Delaware Street perimeter fence line.	0.076	Not co-located with a dust monitor.
6/19/09	061909-WH-PGS2	On Grove Street perimeter fence line; approximately 190 feet down from the corner of Grove and Delaware Streets; down wind of the Containment Area.	<0.098	Not co-located with a dust monitor.
6/19/09	061909-WH-AM3	Downwind of Grove Street excavation.	<0.062	Air Monitor #3
6/19/09	061909-WH-PDS1	On the southern side of Delaware Street on the wooden sign.	<0.066	Not co-located with a dust monitor.
6/19/09	061909-WH-PDS2	Delaware Street perimeter fence line.	<0.065	Not co-located with a dust monitor.
6/19/09	061909-WH-AM2	South of the Containment Area, Sulphur Creek Monitoring.	<0.092	Air Monitor #2